

Eugene School District 4J  
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw				Follow Up - New Fixture Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)	Additional Action	Date Sampled	Sample ID #	Result (ppb)
<b>Coburg Community Charter School</b>															
Cafeteria	Fountain	7/8/2016	COBES-I-001	11.60											
Kitchen Prep	Sink	7/8/2016	COBES-I-002	29.30	9/8/2016	COBES-F-050	2.82	9/14/2016	9/15/2016	COBES-I-052	5.96				
Kitchen Big	Sink	7/8/2016	COBES-I-003	94.00	9/8/2016	COBES-F-049	4.41	9/14/2016	9/15/2016	COBES-I-053	33.00	Replaced Utility Sink, Angle Stops, old plumbing fittings within wall opening.	10/7/2016	COBES-I-054	3.72
Kitchen Little	Sink	7/8/2016	COBES-I-004	2.79											
Kitchen Dishwash Sprayer	Sink	7/8/2016	COBES-I-005	8.04											
Room 1	Sink	7/8/2016	COBES-I-006	3.90											
Room 1	Fountain	7/8/2016	COBES-I-007	4.13											
Room 2	Sink	7/8/2016	COBES-I-008	8.82											
Room 2	Fountain	7/8/2016	COBES-I-009	1.74											
Room 3	Sink	7/8/2016	COBES-I-010	4.77											
Room 3	Fountain	7/8/2016	COBES-I-011	6.09											
Computer Room	Sink	7/8/2016	COBES-I-012	15.10											
Exterior Playground	Fountain	7/8/2016	COBES-I-013	4.87											
Boys Restroom (South) at Room 4	Sink	7/8/2016	COBES-I-014	8.90											
Boys Restroom (North) at Room 4	Sink	7/8/2016	COBES-I-015	15.80											
Girls Restroom (South) at Room 4	Sink	7/8/2016	COBES-I-016	5.04											
Girls Restroom (North) at Room 4	Sink	7/8/2016	COBES-I-017	11.50											
Room 4	Sink	7/8/2016	COBES-I-018	5.85											
Room 4	Fountain	7/8/2016	COBES-I-019	5.33											
Staff Room	Sink	7/8/2016	COBES-I-020	3.68											
Room 5	Sink	7/8/2016	COBES-I-021	37.80	9/8/2016	COBES-F-048	3.01	9/14/2016	9/15/2016	COBES-I-051	2.07				
Room 5	Fountain	7/8/2016	COBES-I-022	5.76											
Boys Restroom (South) at Room 6	Sink	7/8/2016	COBES-I-023	1.89											
Boys Restroom (North) at Room 6	Sink	7/8/2016	COBES-I-024	3.50											
Room 6	Sink	7/8/2016	COBES-I-025	9.09											
Room 6	Fountain	7/8/2016	COBES-I-026	1.69											
Hall at Room 6	Fountain	7/8/2016	COBES-I-027	2.56											
Girls Restroom (South) at Room 7	Sink	7/8/2016	COBES-I-028	1.72											
Girls Restroom (North) at Room 7	Sink	7/8/2016	COBES-I-029	2.38											
Room 7	Sink	7/8/2016	COBES-I-030	9.77											
Room 7	Fountain	7/8/2016	COBES-I-031	8.69											
Room 8	Sink	7/8/2016	COBES-I-032	10.50											
Room 8	Fountain	7/8/2016	COBES-I-033	1.25											
Staff Room	Sink	7/8/2016	COBES-I-034	8.14											
Office Health Room	Sink	7/8/2016	COBES-I-035	5.80											
Office	Sink	7/8/2016	COBES-I-036	4.56											
Office Restroom	Sink	7/8/2016	COBES-I-037	3.44											
Library	Sink	7/8/2016	COBES-I-038	4.17											
Library	Fountain	7/8/2016	COBES-I-039	2.71											
Hall at Library	Fountain	7/8/2016	COBES-I-040	ND											
Room 10	Sink	7/8/2016	COBES-I-041	4.22											
Room 10	Insta-Hot	7/8/2016	COBES-I-042	ND											
Room 11	Sink	7/8/2016	COBES-I-043	11.00											
Gym Hall (South)	Fountain	7/8/2016	COBES-I-044	3.67											
Gym Girls Restroom	Sink	7/8/2016	COBES-I-045	6.71											
Gym Boys Restroom	Sink	7/8/2016	COBES-I-046	13.80											
Gym Hall (North)	Fountain	7/8/2016	COBES-I-047	1.42											
Staff Room Refrigerator - In Freezer	Ice Machine	10/13/2016	COBES-I-055	6.46											

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.